


### Junk Lead Seal PS-TP

The Junk Lead Seal PS-TP is used to define the position of tool in string during repair-and-recovery works in the well. The Junk Lead Seal consists of a body with connecting thread and lead mould that is tightly attached and prevent its leaving on the bottom. There is a groove for washing up. Lead plasticity gives an opportunity to get a seal of tool in the well.



Code	Outside diameter, in	Length, ft	Thickness of lead, in	Washing channel diameter, in	Weight, lb	Connecting thread
<b>PS-55TP</b>	2.17	0.72	1.38	0.63	8.16	AMMT
<b>PS-60 TP</b>	2.36	0.72	1.57	0.63	8.82	AMMT
<b>PS-65 TP</b>	2.56	0.72	1.57	0.63	9.04	AMMT
<b>PS-70 TP</b>	2.76	0.72	1.77	0.63	9.04	AMMT
<b>PS-75 TP</b>	2.95	0.75	1.77	0.63	9.26	AMMT
<b>PS-80 TP</b>	3.15	0.75	1.77	0.63	9.7	AMMT
<b>PS-85 TP</b>	3.35	0.77	1.77	0.63	10.36	AMMT